




Appendix Dimensioning Symbols




H = LETTER HEIGHT


DIMENSIONING SYMBOLS




H = LETTERING HEIGHT



DATUM FEATURE SYMBOL



DATUM TARGET SYMBOL



DATUM FEATURE AND DATUM TARGET SYMBOL


A3

Appendix Material Condition Symbols

Ⓜ MMC, MAXIMUM MATERIAL CONDITION


RFS, REGARDLESS OF FEATURE SIZE
NO SYMBOL, RFS IS ASSUMED
UNLESS OTHERWISE SPECIFIED

Ⓛ LMC, LEAST MATERIAL CONDITION




MATERIAL CONDITION SYMBOLS

Appendix Feature Control Frame



H = LETTERING HEIGHT



GEOMETRIC CHARACTERISTIC SYMBOL

DIAMETER SYMBOL (when used)
ZONE DESCRIPTOR

GEOMETRIC TOLERANCE

MATERIAL CONDITION SYMBOL

TERTIARY DATUM REFERENCE

MATERIAL CONDITION SYMBOL (when used)

SECONDARY DATUM REFERENCE

PRIMARY DATUM REFERENCE

FEATURE CONTROL FRAME

A5

Appendix Geometric Characteristic Symbols and Related Geometric Tolerancing Symbols

